



®

DSX Access Systems, Inc.

## PDM to CDM Power Connections

### DSX-1040PDM to 1040CDM Power Connections

This diagram shows the power connections between the DSX-1040PDM and the DSX-1040CDM modules. Notice there are 4 - 18awg wires leaving terminals 4,5,6,7 on the PDM and that they all connect to terminal 13 (+) and 15 (-) on the CDM. Not making these connections properly could leave the system under-powered.

